

testing u. .

12 December, 1969

MEMORANDUM TO: CHIEF, [REDACTED]
 FROM : SAFE TECHNICIAN, [REDACTED]
 SUBJECT : VISIT TO BUREAU OF STANDARDS TO VIEW A TESTED HILLSIDE CLASS V
 CABINET

On the 11th of December 1969 I accompanied Mr. [REDACTED] Mr. [REDACTED] and Mr. [REDACTED] from the Physical Sec. Division to inspect a Class V Hillside cabinet which turned out to be the one that was submitted for testing for acceptance, by Hillside metal products of Newark, N.J. The unit was apparently tested by a Mr. Williard (now deceased). Upon close examination of this cabinet, which was a 5 drawer Class V, it was found that the type of drawer suspensions used in this test model were not the same as those drawer suspensions which came equipped on the Class V Hillside Cabinets which were delivered to our [REDACTED] of which 5 were transhipped here to [REDACTED]. We were also invited to look at a Hillside Class 6 cabinet while we were there and after close examination of this Class 6 cabinet it was quite apparent that the suspensions delivered with our Class V's from Hillside were identical to the suspensions on the Class 6 Hillside. ~~was checked~~
 nix

It was the consensus of Mr. [REDACTED] Mr. [REDACTED] Mr. [REDACTED] and myself that we should ask GSA to run a cycle test on one of our cabinets here at [REDACTED] to see whether or not the suspensions we had delivered with our Hillside Class V's will hold up. Mr. Bland and Mr. Harold of GSA agreed to run this test and it was at this point that we terminated our visit and returned to our respective buildings.

Since it is not possible for me to preclude whether or not the difference in the type of suspension between the Class V submitted for test and those delivered to us was intentional or accidental it casts a shadow of doubt in my mind as to whether or not the cabinet originally delivered to Mr. Williard at the Bureau of Standards is of the same specifications as the Class V cabinet delivered to our Agency.

According to [REDACTED] of our Physical Security Division it is practically impossible to procure any written reports on the results of the testing by Mr. Williard of the Bureau on the Hillside Class V cabinet. It is only SOP that whenever a cabinet submitted for test fails and the manufacturer insists on a written report is it customary to produce such a report of the results.

RECOMMENDATION: That we request GSA to run the cycle test and possibly a re-testing of the Class V Hillside Cabinet as a whole.

MORI/CDF

LABORATORY TEST RECORD

1. LABORATORY TEST NO.

3701591

2. PROGRAM		CODES		COMMODITY AREA	
S-Stores NS-Nonstores FSS-Federal Supply Schedules		TRANSACTION A-Origin B-Destination C-QA Verification D-Complaint E-Bid Sample F-Interwarehouse Transfer G-Warehouse Surveillance		1-Paints, Coatings, 3-Physical Adhesives 4-Paper 2-Chemical 5-Textile	
3. FEDERAL STOCK NO.		4. SPECIFICATION NO.			
5. MATERIAL		6. MANUFACTURER (Name)			
Security File Cabinet		Hillside Metal Products, Inc.			
7. CONTRACT/INVITATION NO.		8. PURCHASE ORDER NO.		9. DATE SAMPLED	
10. LOT/BATCH NO.	11. LOT SIZE	12. SAMPLE SIZE	13. VALUE OF LOT	14. PROGRAM CODE	15. TRANSACTION CODE
			\$		
16. SUBMITTED BY		17. REGION		FOR USE OF QUALITY CONTROL DEPOT PERSONNEL	
Mr. J. F. Lewless, C. O.				18. DATE OF DELIVERY 19. OCD NOTIFIED 20. DISCOUNT TERMS	
21. REMARKS (For use of QCR/QCI)					

22. TEST REQUIREMENTS	23. TEST RESULTS
Second Draw (Combination Lock Draw)	
Par. 4.4.4.2 Service Test	DOES NOT CONFORM Handle pulled off and replaced 3074 cycles. Handle about to pull off again 4270 cycles.
Par. 4.4.4.3 Draw pull test - 10 lbs. Max.	DOES NOT CONFORM Initial Pull - 11 lbs. - 102. DOES NOT CONFORM At 3074 Cycles - 17 lbs - 6.25 oz. DOES NOT CONFORM At 4270 Cycles - Over 22 lbs. 2.25 oz.
Par. 4.4.4.2 Service Test	Does not comply - Stopped after 8100 cycles. DOES NOT CONFORM
Par. 4.4.4.3 Draw pull test - 10 lbs. Max.	DOES NOT CONFORM Initial Pull - 8 lbs. 2 oz. DOES NOT CONFORM At 3492 Cycles - 10 lbs. 3.5 oz. DOES NOT CONFORM At 8100 Cycles - 10 lbs. 4 oz.

FOR LABORATORY USE

24. REGION NO.	25. COMMODITY AREA CODE	26. DATE RECEIVED	27. DATE ASSIGNED	28. ASSIGNED TO
		1/12/70	1/20/70	Paul W. Scott
29. LABORATORY DECISION (Check)				30. DISPOSITION OF REMINDER
a. <input type="checkbox"/> COMPLIES b. <input checked="" type="checkbox"/> DOES NOT COMPLY c. <input type="checkbox"/> NO TEST MADE d. <input type="checkbox"/> ANALYSIS ONLY				a. <input type="checkbox"/> HELD b. <input type="checkbox"/> DESTROYED c. <input type="checkbox"/> RETURNED TO STOCK d. <input type="checkbox"/> SALVAGE
31. AMOUNT CONSUMED				32. COST OF RETEST
				\$
33. ANALYST (Signature)		DATE	34. CHIEF, RST BRANCH (Signature)	
/s/ Paul W. Scott		1/23/70	(Signed) Paul W. Scott	
DATE		DATE		
1/23/70		1/23/70		

GENERAL SERVICES ADMINISTRATION
• GPO: 1969-321-377

GSA DC 68-9475

GSA FORM JAN 68 309